

Boot Software Version prom-E3.3.0.0, Built Apr 10 2003 13:18:37
Processor: R5000 rev 2.1 [0x2321], 198 MHz, (bus: 66 MHz), 64 MB DRAM
I-Cache 32 KB, linesize 32. D-Cache 32 KB, linesize 32.
L2-Cache 512 KB, linesize 32, cache enabled.

Mounting 8MB Linear external flash card . . . Verifying the file system . . . Done
Autoboot in 2 seconds - press ESC to abort and enter prom

using link: bootsource
link pointed at file:/pc-flash/boot/ssr_ma~1.tar/
source: file:/pc-flash/boot/ssr_ma~1.tar/
Loaded version file
Loading kernel (base 0x80001000, size 50592)
(base 0x8000d5a0, size 4876738)
100% - Image checksum validated

XP-8600 System Software, Version E10.00.20.0002
Copyright (c) 2007, Enterasys Networks
Built by slcbuild@slc-bld3 on Fri May 30 17:41:35 2008
Processor: R5000, Rev 2.1, 198.00 MHz
System started on 2019-09-13 12:38:32

2019-09-13 12:38:33 %SYS-I-FLASHCRD, Mounting 8MB Flash card
2019-09-13 12:38:33 %SYS-I-FLASHMNTD, 8MB Flash card mounted
2019-09-13 12:38:33 %SYS-I-INITSYS, initializing system XP-8600
2019-09-13 12:38:33 %SYS-I-DSCVMOD, discovered 'Control Module (XP-8/16 CM2)' module in slot CM
2019-09-13 12:38:38 %SYS-I-MULTICPU, additional Control Module detected in slot CM/1
2019-09-13 12:38:38 %SYS-I-INITSLOTS, Initializing system slots - please wait
2019-09-13 12:38:51 %SYS-I-MODPROBE, Detecting installed media modules - please wait
2019-09-13 12:38:51 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 2
2019-09-13 12:38:51 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 3
2019-09-13 12:38:51 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 4
2019-09-13 12:38:51 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 5
2019-09-13 12:38:51 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 6
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 7
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered '16-10/100-TX "T"' module in slot 8
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 9
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered '10/100-TX' module in slot 10
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered 'Gigabit-SX' module in slot 11
2019-09-13 12:38:52 %SYS-I-DSCVMOD, discovered '10/100-TX' module in slot 12
2019-09-13 12:38:53 %SYS-I-DSCVMOD, discovered '4-Gigabit-TX "T"' module in slot 14
2019-09-13 12:39:11 %SYS-I-INITPORT, initialized slot 2, port 1
2019-09-13 12:39:11 %SYS-I-INITPORT, initialized slot 2, port 2
2019-09-13 12:39:12 %SYS-I-INITPORT, initialized slot 3, port 1
2019-09-13 12:39:13 %SYS-I-INITPORT, initialized slot 3, port 2
2019-09-13 12:39:14 %SYS-I-INITPORT, initialized slot 4, port 1
2019-09-13 12:39:14 %SYS-I-INITPORT, initialized slot 4, port 2
2019-09-13 12:39:15 %SYS-I-INITPORT, initialized slot 5, port 1
2019-09-13 12:39:16 %SYS-I-INITPORT, initialized slot 5, port 2
2019-09-13 12:39:17 %SYS-I-INITPORT, initialized slot 6, port 1
2019-09-13 12:39:18 %SYS-I-INITPORT, initialized slot 6, port 2
2019-09-13 12:39:18 %SYS-I-INITPORT, initialized slot 7, port 1
2019-09-13 12:39:19 %SYS-I-INITPORT, initialized slot 7, port 2
2019-09-13 12:39:19 %SYS-I-INITPORT, initialized slot 8, port 1
2019-09-13 12:39:19 %SYS-I-INITPORT, initialized slot 8, port 2
2019-09-13 12:39:19 %SYS-I-INITPORT, initialized slot 8, port 3
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 4
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 5
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 6
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 7
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 8
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 9
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 10
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 11
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 12
2019-09-13 12:39:20 %SYS-I-INITPORT, initialized slot 8, port 13
2019-09-13 12:39:21 %SYS-I-INITPORT, initialized slot 8, port 14
2019-09-13 12:39:21 %SYS-I-INITPORT, initialized slot 8, port 15
2019-09-13 12:39:21 %SYS-I-INITPORT, initialized slot 8, port 16
2019-09-13 12:39:22 %SYS-I-INITPORT, initialized slot 9, port 1
2019-09-13 12:39:22 %SYS-I-INITPORT, initialized slot 9, port 2
2019-09-13 12:39:22 %SYS-I-INITPORT, initialized slot 10, port 1
2019-09-13 12:39:22 %SYS-I-INITPORT, initialized slot 10, port 2
2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 3
2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 4
2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 5
2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 6
2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 7

2019-09-13 12:39:23 %SYS-I-INITPORT, initialized slot 10, port 8
2019-09-13 12:39:24 %SYS-I-INITPORT, initialized slot 11, port 1
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 11, port 2
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 1
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 2
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 3
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 4
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 5
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 6
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 7
2019-09-13 12:39:25 %SYS-I-INITPORT, initialized slot 12, port 8
2019-09-13 12:39:27 %SYS-I-INITPORT, initialized slot 14, port 1
2019-09-13 12:39:28 %SYS-I-INITPORT, initialized slot 14, port 2
2019-09-13 12:39:29 %SYS-I-INITPORT, initialized slot 14, port 3
2019-09-13 12:39:30 %SYS-I-INITPORT, initialized slot 14, port 4
2019-09-13 12:39:31 %SYS-I-PWRKAY, power supply in slot PS1 is operational
2019-09-13 12:39:31 %SYS-I-NOPWRSPLY, power supply in slot PS2 not present or not turned on
2019-09-13 12:39:31 %SYS-I-FANSOKAY, system fans are operational
2019-09-13 12:39:32 %SYS-I-DSCVMOD, discovered 'Switching Fabric' module in slot Fabric 1
2019-09-13 12:39:32 %SYS-I-ACTIVEBKPLANE, 'Switching Fabric' in slot 'Fabric 1' is currently active
2019-09-13 12:39:32 %SYS-I-TEMPKAY, system temperature is within operating parameters
IPsec: Initialized Security Association Processing.
2019-09-13 12:39:32 %L2TM-I-INIT, L2 Table Manager initialized
2019-09-13 12:39:32 %GATED-I-START, Started (pid 0x8162a9e0).
SNMP Research SNMP Agent Resident Module Version 15.1.6.0
Copyright 1989, 1990, 1991, 1992, 1993, 1994, 1995, 1996, 1997, 1998 SNMP Research, Inc.
2019-09-13 12:39:33 %SNMP-I-RMON_ENABLED, RMON Agent enabled
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.2.1 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.2.2 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.3.1 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.3.2 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.4.1 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.4.2 - Port Down
2019-09-13 12:39:33 %STP-I-PORT_STATUS, Port status change detected: gi.5.1 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: gi.5.2 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: gi.6.1 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: gi.6.2 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: gi.7.1 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: gi.7.2 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.1 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.2 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.3 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.4 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.5 - Port Down
2019-09-13 12:39:34 %STP-I-PORT_STATUS, Port status change detected: et.8.6 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.7 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.8 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.9 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.10 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.11 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.12 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.13 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.14 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.15 - Port Down
2019-09-13 12:39:35 %STP-I-PORT_STATUS, Port status change detected: et.8.16 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: gi.9.1 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: gi.9.2 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.1 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.2 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.3 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.4 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.5 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.6 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.7 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: et.10.8 - Port Down
2019-09-13 12:39:36 %STP-I-PORT_STATUS, Port status change detected: gi.11.1 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: gi.11.2 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.1 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.2 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.3 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.4 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.5 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.6 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.7 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: et.12.8 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: gi.14.1 - Port Down
2019-09-13 12:39:37 %STP-I-PORT_STATUS, Port status change detected: gi.14.2 - Port Down
2019-09-13 12:39:38 %STP-I-PORT_STATUS, Port status change detected: gi.14.3 - Port Down

2019-09-13 12:39:38 %STP-I-PORT_STATUS, Port status change detected: gi.14.4 - Port Down

Press RETURN to activate console . . .

2019-09-13 12:39:38 %SNMP-I-ENABLED, SNMP Agent enabled

2019-09-13 12:39:38 %SYS-I-NETSTART, network interfaces are now enabled

2019-09-13 12:39:56 %SYS-W-NOPASSWD, no password for login, use 'system set password' in Config mode

2019-09-13 12:39:56 %CONS-A-LOGIN, Console user (Unknown), Console user login

xp> 2019-09-13 12:39:58 %SNMP-I-AGENT_READY, SNMP agent is now ready to send and receive packets